

## Inspection Photos

Location Name: Gunderson 20-03 Pad and Spill/Release

Location ID: #449070 & Spill/Release ID: #483326

Inspection Date: July 4, 2023



Photo #1 – Sign at entrance to pad.



Photo #2 – Open excavation related to Spill/Release ID #483326 at NE corner of pad.





## Inspection Photos

Location Name: Gunderson 20-03 Pad and Spill/Release

Location ID: #449070 & Spill/Release ID: #483326

Inspection Date: July 4, 2023



**Photo #3 – Stormwater ditch leading off NE corner of pad was spill path for Spill/Release ID #483326.**



**Photo #4 – Fenced area NW of pad was impacted by Spill/Release ID #483326 and is subject of Remediation Project #27161.**





## Inspection Photos

Location Name: Gunderson 20-03 Pad and Spill/Release

Location ID: #449070 & Spill/Release ID: #483326

Inspection Date: July 4, 2023



COGCC Field Inspection  
39.26727, -107.79436, 7106.0ft, 220°  
07/04/2023 10:34:00 AM

**Photo #5 – Overview of pad from NE.**



COGCC Field Inspection  
39.26691, -107.79535, 7105.0ft, 27°  
07/04/2023 10:37:41 AM

**Photo #6 – Localized accumulation of oily waste beneath 20-06W wellhead.**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources




## Inspection Photos


Location Name: Gunderson 20-03 Pad and Spill/Release

Location ID: #449070 & Spill/Release ID: #483326

Inspection Date: July 4, 2023



**Photo #7 - Localized accumulation of oily waste beneath 20-07W wellhead.**



**Photo #8 - Localized accumulation of oily waste beneath 20-08W wellhead.**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: Gunderson 20-03 Pad and Spill/Release

Location ID: #449070 & Spill/Release ID: #483326

Inspection Date: July 4, 2023



**Photo #9 - Localized accumulation of oily waste beneath 20-04E wellhead.**



**Photo #10 – Accumulation of oily waste inside of secondary containment device at wellhead day tank pump.**