

# Inspection Photos

Location Name: Nichols 24-06 Pad

Location ID: #334504

Inspection Date: July 4, 2023



Photo #1 – Sign at entrance to pad.

Photo #2 - Tire ruts at entrance to pad.



## Inspection Photos

Location Name: Nichols 24-06 Pad

Location ID: #334504

Inspection Date: July 4, 2023



**Photo #3 – Rutted area SW of tank battery.**



**Photo #4 – View into tank battery secondary containment area.**

## Inspection Photos

Location Name: Nichols 24-06 Pad

Location ID: #334504

Inspection Date: July 4, 2023



**Photo #5 – Rutted area along NW side of pad.**



**Photo #6 – Rutted area SW of wellheads.**



**Inspection Photos**  
**Location Name: Nichols 24-06 Pad**  
**Location ID: #334504**  
**Inspection Date: July 4, 2023**



**Photo #7 – Tire ruts along NW side of wells.**

**Photo #8 – Uncapped production pipe located at Nichols 24-5 wellhead.**

## Inspection Photos

Location Name: Nichols 24-06 Pad

Location ID: #334504

Inspection Date: July 4, 2023



**Photo #9 - Uncapped production pipe located at Nichols 24-10 wellhead.**



**Photo #10 – Separators located at NE end of pad.**



## Inspection Photos

Location Name: Nichols 24-06 Pad

Location ID: #334504

Inspection Date: July 4, 2023



COGCC Field Inspection  
39.26484, -107.83156, 7090.6ft, 109°  
07/04/2023 10:16:37 AM



COGCC Field Inspection  
39.26488, -107.83147, 7091.2ft, 97°  
07/04/2023 10:16:50 AM

**Photo #11 - Uncapped production pipe located at Nichols 24-5 separator.**

**Photo #12 - Uncapped production pipe located at Nichols 24-10 separator.**

