

Inspection Photos

Loc: 470757

Operator: WESTERN OPERATING COMPANY

Inspection Date: 7/6/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Loc: 470757 | Date: 7/6/2023

Inspection Photos



Photo 1. Drone aerial photo facing west toward the PYLES offsite tank battery and storage yard. The use of this location as a storage yard is prohibited per the rules. All unused equipment and supplies must be removed and interim reclamation must be performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 470757 | Date: 7/6/2023

Inspection Photos



Photo 2. There is unused equipment being stored on location that needs to be removed. All equipment and supplies not necessary for use on this Oil and Gas Location is prohibited per Rule 606 and 1003.a.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Loc: 470757 | Date: 7/6/2023

Inspection Photos



Photo 3. Facing west at the south side of the location. There is equipment and a vehicle that appears to have been sitting unused at this location for awhile.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 470757 | Date: 7/6/2023

Inspection Photos



Photo 4. Facing toward the PYLES offsite tank battery at the location. There is still stained soil at the outlet and oil fluid inside the plastic containment.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Loc: 470757 | Date: 7/6/2023

Inspection Photos



Photo 5. The shed inside the containment battery is not maintained with metal siding laying on the ground.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 470757 | Date: 7/6/2023

Inspection Photos



Photo 6. Facing at the back side of the tank battery. There was a spill from the tank which needs to be cleaned up. The blue bucket needs to be emptied and disposed of any oil.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 470757 | Date: 7/6/2023

Inspection Photos



Photo 7. This bucket t the backside of the tank battery is full of oil which has spilled onto the ground.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 470757 | Date: 7/6/2023

Inspection Photos



07.06.2023

Photo 8. Facing toward the southwest side of the location. There is concrete debris and a broken bottom of a tank among other debris and equipment that must be removed per Rule 606 & 1003.a.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 470757 | Date: 7/6/2023

Inspection Photos



Photo 9. Facing southeast toward the PYLES offsite tank battery and storage yard. There is concrete debris and a broken bottom of a tank among other debris and equipment that must be removed per Rule 606 & 1003.a.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Loc: 470757 | Date: 7/6/2023

Inspection Photos



Photo 10. Facing northeast toward the PYLES offsite tank battery and storage yard.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 470757 | Date: 7/6/2023

Inspection Photos



Photo 11. There is various parts and supplies being stored on location. All equipment and supplies not necessary for use on this Oil and Gas Location is prohibited per Rule 606 and 1003.a.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Loc: 470757 | Date: 7/6/2023

Inspection Photos



Photo 12. There are several chemical barrels on location with faded labeling and no secondary containment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 470757 | Date: 7/6/2023

Inspection Photos



Photo 13. There are various parts and supplies in this area that need to be removed. The two buckets of oil have been removed however stain soils are still evident shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 470757 | Date: 7/6/2023

Inspection Photos



Photo 14. Facing east at the north side of the location. There is storage of unused drilling pipe, trailers, ect. All equipment and supplies not necessary for use on this Oil and Gas Location is prohibited per Rule 606 and 1003.a.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 470757 | Date: 7/6/2023

Inspection Photos



Photo 15. Facing toward the east side of the location. All equipment and supplies not necessary for use on this Oil and Gas Location is prohibited per Rule 606 and 1003.a.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 470757 | Date: 7/6/2023

Inspection Photos



Photo 16. Facing southwest at the location PYLES offsite tank battery and storage yard. The use of this location as a storage yard is prohibited per the rules.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Loc: 470757 | Date: 7/6/2023