00212711

WELL SITE INSPECTION FORM

WELL NAME Altergott #1 API NUMBER 05 - -
OPERATOR Nautilus Equip. Co. PERMIT NUMBER
LOCATION SWSE 22-6N-67W COUNTY Weld
FIELD La Poudre South INSPECTOR SP

AL/PA/DA INSPECTION RESULTS: WELL STATUS:
PASS(Y)___ FAIL(N)___ DATE___ FN___ FD___ WO___

==========

DATE OF INSPECTION BEFORE/DURING DRILLING___

CASING SIZE___ DEPTH SET___ CMT VOL___ WOC___
CONSISTENT WITH APD CASING PROGRAM?___ RETURNS___
RIG___ BOP'S___ CONTACT___

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION 5/11/88

PIPE SET?___ COMPLETION RIG/ACTIVITY___
DRILLING PITS: CLOSED___ OPEN___ WELLHEAD SYSTEM INSTALLED ✓
TANK ID: YES___ NO ✓ NA___ WELL SIGN: YES___ NO ✓
SKIM PIT: ___ gal TANKS: (2) 300 bbls
EQUIPMENT flowing well
BRADENHEAD PRESSURE ___ FLUID: NO___ YES___ TYPE___
METER RUN: YES ✓ NO___ WELL STATUS: PR ✓ TA___ SI___ WELL CAT 3-d

AL/PA/DA INSPECTION

DATE PLUGGED:___ DATE PERMIT EXPIRED:___
HOLE PLUGGED: YES___ NO___ PITS BACKFILLED: YES___ NO___
MATERIAL BURIED: YES___ NO___ NA___ SITE CLEAN: YES___ NO___
BOND RELEASE OK: YES___ NO___ FED___ HOLE MARKER: YES___ NO___

DATE OF SAFETY/STATUS INSPECTION___

COMMENTS___