



---

## **Wolf 12L liner inspection**

---

Photo log of liner inspection

7/5/2023 - Pea Gravel removed from around release location.



20230705\_110011.jpg

## 7/5/2023 - Pea gravel removal



20230705\_110014.jpg

---

7/5/2023 - Double containment boom



20230705\_110051.jpg

7/5/2023 - Pea gravel removal



20230705\_110156.jpg

---

## 7/5/2023 - Containment walls in good condition



20230705\_110522.jpg

---

**7/5/2023 - Containment walls in good condition**



20230705\_110536.jpg

## 7/5/2023 - Containment walls in good condition



20230705\_110734.jpg

---

## 7/5/2023 - Containment walls and working Vac



20230705\_110737.jpg

---