



Advanced Technologies
Waste Management Support
Environmental Services
Staff Augmentation

Native American and Women Owned
8(a) Small Business

July 6, 2023
Sydney Smith
Fundare Resource Company
56719 CR 127
New Raymer, CO 80742
RE: Liner Inspection
Razor 12F
Weld County, Colorado

RPT-FTCOL-23-38

Sydney:

On July 5, 2023, MarCom LLC (MarCom) was contracted by Fundare to conduct a site inspection at the Wolf 12L release and complete a liner inspection at the (Site) in Weld County, Colorado. The purpose of the inspection event was to ensure that all hydrocarbon released were contained and did not leave the containment. The initial release was reported under document number 403447860.

On July 5, 2023, Following the removal of the Pea Gravel from the boomed area within the secondary containment, MarCom personnel conducted a liner inspection of the containment surrounding the Wolf 12L release. The inspector found a clean liner with no signs of damage, and the overall integrity of the liner was in good shape. A photo doc attached shows the liner and containment.

Following the removal of the Pea Gravel Fundare contractors transported and disposed of the material at an approved landfill facility. Clean Pea Gravel will be brought into the containment upon approval of this closure request. Based upon the inspection MarCom believes that no impacts left the containment, and no further corrective action is necessary, and that Fundare can request closure from the COGCC. If you have any questions or comments, please do not hesitate to call me at (970) 237-1415.

Respectfully Submitted,
Levi Kirk
Project Manager
MarCom LLC

Idaho Falls, ID
525 Park Avenue, Suite 2E
Idaho Falls, ID 83402
Phone: 208-538-1782


Butte, MT
65 E Broadway, Suite 200
Butte, MT 59701
Phone: 208-390-8301

Fort Collins, CO
1811 E. Mulberry Street
Fort Collins, CO 80524
Phone: 208-201-8280


<https://www.marcom-services.com/>



Legend
X Site Location



Wolf 12L Site Location

	Date: 07.07.23 Creator: BR
---	-------------------------------



Wolf 12L liner inspection

Photo log of liner inspection

7/5/2023 - Pea Gravel removed from around release location.



20230705_110011.jpg

7/5/2023 - Pea gravel removal



20230705_110014.jpg

7/5/2023 - Double containment boom



20230705_110051.jpg

7/5/2023 - Pea gravel removal



20230705_110156.jpg

7/5/2023 - Containment walls in good condition



20230705_110522.jpg

7/5/2023 - Containment walls in good condition



20230705_110536.jpg

7/5/2023 - Containment walls in good condition



20230705_110734.jpg

7/5/2023 - Containment walls and working Vac



20230705_110737.jpg
