

Inspection Photos
Location Name: KLEIN/B16-99HZ
Location ID: 420631



Photo #1

Klein B16-98HZ (123-32651) Wellsite

Plugged & Abandoned | PA

NOT Cut / Capped

CA: Well sign NOT posted



Photo #2

Klein B15-13D, B16-98HZ, B16-99HZ Battery site

Abandoned: ALL Equipment Removed