

Inspection Photos
Location Name: McCrumb 1
Location ID: 317748



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: McCrumb 1
Location ID: 317748




Photo 3 Pump Jack.



Photo 4 Weeds growing around ancillary equipment.

Inspection Photos
Location Name: McCrumb 1
Location ID: 317748



Photo 5 TB sign.



Photo 6 TB.

Inspection Photos
Location Name: McCrumb 1
Location ID: 317748



Photo 7 Unmarked, uncapped flow line not LOTO.



Photo 8 Unmarked, uncapped flow line not LOTO.

Inspection Photos
Location Name: McCrumb 1
Location ID: 317748



Photo 9 Horizontal Heated Separator.



Photo 10 Gas Meter Run, no indication of calibration status.

Inspection Photos
Location Name: McCrumb 1
Location ID: 317748



Colorado Energy & Carbon Management Commission
40.1366, -104.79789, 4886.3ft
07/06/2023 12:30:37

Photo 11 Produced water vessel.