

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/07/2023

Submitted Date:

07/07/2023

Document Number:

702402052**FIELD INSPECTION FORM**Loc ID 317748 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	All Inspections
,		cogcc@kpk.com	All Inspections
Silver, Randy		randy.silver@state.co.us	
Adamczyk, Megan		megan.adamczyk@state.co.us	complaint inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239912	WELL	PR	12/07/2001	OW	123-07700	MCCRUMB 1	PR
470370	TANK BATTERY	AC	12/20/2019		-	McCrumb 1 & 2 battery	AC

General Comment:

Inspected Facilities			
Facility ID: <u>239912</u>	Type: <u>WELL</u>	API Number: <u>123-07700</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment: <u>PR</u>			
Corrective Action:		Date:	
BradenHead			
Date of Last Brhd Test: <u>01/16/2023</u>		Annual Brhd Completed? <u>Yes</u>	
Last Brhd Test Results		Initial Surf Csg Pressure: <u>0</u>	Fluid Type: _____
		End Surf Csg Pressure: <u>0</u>	
Comment: _____			
Corrective Action: _____		Date: _____	
Complaint			
Comment:		<p>Inspection in response to complaint. Compliance Specialist Assigned: Robbie Revas Complaint Received Date: 7-6-2023 Complaint Contacted: No Date: Time: Facility ID: # 470370 & Location ID: 317748 Location name: McCrumb #1 & McCrumb 1&2 Battery Inspection Document # 702402044 Complaint inspection document # 702402052 Complaint Document form 18 # 403452998 Nature of Complaint: Air quality/odor. Field Inspector Actions: On 7-6-2023, I Robbie Revas area Compliance Specialist was assigned a complaint received by COGCC staff in reference to Air quality/Odor. The complainant stated the issues were at the well location. The complainant's detailed description of the issues are in the form 18. On 7-6-23, I performed a complete site inspection of the well location & tank battery. At time of inspection, I did not hear the Separator leaking or smell any unusual odors at the time of the inspection. Both wells attached to the battery are SI. I did write up compliance issues, you can find them in my prior inspection document, above on the COGCC website. Weather Conditions: Cloudy & warm. Location: Muddy Violations of COGCC rules were observed at the time of the inspection. All information has been reviewed and site inspection information has been submitted to the COGCC for further review.</p>	
Corrective Action:		Date:	
COGCC Comments			
Comment		User	Date
<u>Inspection due to a complaint Form 18 Doc # 403452998</u>		<u>revasr</u>	<u>07/07/2023</u>
Attached Documents			
You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:			
Document Num	Description	URL	
<u>702402053</u>	<u>location pics</u>	<u>http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6173500</u>	