

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 92-29 Pad

Location ID: 324090



Photo # 2506 From entrance to location



Photo # 2507 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 92-29 Pad

Location ID: 324090



Photo # 2508 Location



Photo # 2509 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 92-29 Pad

Location ID: 324090



Photo # 2512 Open ended load line