



00203985

## WELL SITE INSPECTION FORM

WELL NAME Atwood East Unit 16  
OPERATOR Monahan  
LOCATION NWSE 25-7N-53W  
FIELD Atwood East

API NUMBER 05 - 075 - 52570  
PERMIT NUMBER \_\_\_\_\_  
COUNTY Logan  
INSPECTOR SP

## AL/PA/DA INSPECTION RESULTS:

PASS(Y) ☒ FAIL(N) \_\_\_\_\_ DATE 4/14/87

## WELL STATUS:

FN \_\_\_\_\_ FD \_\_\_\_\_ WO \_\_\_\_\_

=====

DATE OF INSPECTION BEFORE/DURING DRILLING \_\_\_\_\_

CASING SIZE \_\_\_\_\_ DEPTH SET \_\_\_\_\_ CMT VOL \_\_\_\_\_ WOC \_\_\_\_\_

CONSISTENT WITH APD CASING PROGRAM? \_\_\_\_\_ RETURNS \_\_\_\_\_

RIG \_\_\_\_\_ BOP'S \_\_\_\_\_ CONTACT \_\_\_\_\_

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION \_\_\_\_\_

PIPE SET? \_\_\_\_\_ COMPLETION RIG/ACTIVITY \_\_\_\_\_

DRILLING PITS: CLOSED \_\_\_\_\_ OPEN \_\_\_\_\_ WELLHEAD SYSTEM INSTALLED \_\_\_\_\_

TANK ID: YES \_\_\_\_\_ NO \_\_\_\_\_ NA \_\_\_\_\_ WELL SIGN: YES \_\_\_\_\_ NO \_\_\_\_\_

SKIM PIT: \_\_\_\_\_ gal TANKS: ( ) \_\_\_\_\_ bbls

EQUIPMENT \_\_\_\_\_

BRADENHEAD PRESSURE \_\_\_\_\_ FLUID: NO \_\_\_\_\_ YES \_\_\_\_\_ TYPE \_\_\_\_\_

METER RUN: YES \_\_\_\_\_ NO \_\_\_\_\_ WELL STATUS: PR \_\_\_\_\_ TA \_\_\_\_\_ SI \_\_\_\_\_ WELL CAT 3- \_\_\_\_\_

## AL/PA/DA INSPECTION

DATE PLUGGED: \_\_\_\_\_ DATE PERMIT EXPIRED: \_\_\_\_\_

HOLE PLUGGED: YES ☒ NO \_\_\_\_\_ PITS BACKFILLED: YES ☒ NO \_\_\_\_\_

MATERIAL BURIED: YES ☒ NO \_\_\_\_\_ NA \_\_\_\_\_ SITE CLEAN: YES ☒ NO \_\_\_\_\_

BOND RELEASE OK: YES ☒ NO \_\_\_\_\_ FED \_\_\_\_\_ HOLE MARKER: YES \_\_\_\_\_ NO \_\_\_\_\_

DATE OF SAFETY/STATUS INSPECTION \_\_\_\_\_

COMMENTS \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_