

Inspection Photos
Location Name: Lost Creek 14
Location ID: 332047



Photo 3 – Wellhead



Photo 4 – Separator

Inspection Photos
Location Name: Lost Creek 14
Location ID: 332047



Photo 5 – NFPA Label on Water Vault



Photo 6 – Tank Battery

Inspection Photos
Location Name: Lost Creek 14
Location ID: 332047



Photo 7 – Tank Battery