

Inspection Photos
Location Name: MorningStar Gallegos 32-5 19-4
Location ID: API 067-06244



Photo #1. Overview of the well location, west and east.

Inspection Photos
Location Name: MorningStar Gallegos 32-5 19-4
Location ID: API 067-06244



Photo #2. View of the 19-2 wellhead assembly.

Inspection Photos
Location Name: MorningStar Gallegos 32-5 19-4
Location ID: API 067-06244



Photo #3. View of the Candelaria 32-5 #20-2 wellhead assembly.

Inspection Photos
Location Name: MorningStar Gallegos 32-5 19-4
Location ID: API 067-06244



Photo #4. View of the 19-4 wellhead assembly.