

Inspection Photos

Location Name: UPRC-65N64W/23NWSE

Location ID: 336624



Photo #1

UPRC-65N64W/23NWSE pad 3: Wellsites

1: Temporarily Abandoned | TA

2: Plugged & Abandoned | PA



Photo #2

Chewy B 23-24 (123-25036) Wellsite

Temporarily Abandoned | TA



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: UPRC-65N64W/23NWSE
Location ID: 336624



Photo #3
Chewy B 23-24 Battery site
Inactive | Shut-down

Formerly served:
UPRC 23-3H4, 23-6H4, CPC-Ferguson 23-1 ;
Plugged & Abandoned | PA



Photo #4
Chewy B 23-24 Battery site
Inactive | Shut-down
Tank(s): SE corner



Inspection Photos
Location Name: UPRC-65N64W/23NWSE
Location ID: 336624



Photo #5
Chewy B 23-24 Battery site
Inactive | Shut-down
Separator(s), ECD(s)



Photo #6
Chewy B 23-24 Battery site
Inactive | Shut-down
Battery sign