

Inspection Photos

Location Name: UPRC-65N64W/23NWSE

Location ID: 336624



Photo #1

UPRC 23-3H4 (123-18089) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 5 yds.



Photo #2

UPRC-65N64W/23NWSE pad 3: Wellsites

1: Temporarily Abandoned | TA

2: Plugged & Abandoned | PA



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: UPRC-65N64W/23NWSE

Location ID: 336624



Photo #3

Chewy B 23-24 Battery site

Inactive | Shut-down

Formerly served:

UPRC 23-3H4, 23-6H4, CPC-Ferguson 23-1 ;

Plugged & Abandoned | PA

Equipment Documented; Loc ID: 336624



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources