

**Operator: CIVITAS NORTH**  
**Location Name: Downtown Directional 1**  
**Loc ID: 432599**  
**Inspection: 694100119**



Exhibit A



Exhibit B



**Exhibit C**

**CA:** Oily stained soil. Please see photos - For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e." For larger instances: "Properly dispose of oily waste in accordance with Rule 905.e and contact area COGCC EPS"

**CA Resolution:** Operator has reported and provided photo evidence that the identified stained soils have been properly addressed and disposed of to comply with Rule 905.e.

**CA:** Weeds present. Please see photos. Weeds need to be removed. Statewide unnecessary equipment, weeds, waste, and trash requirements. Comply with Rule 606.

**CA Resolution:** Operator has reported that the weeds/debris identified on the location has been addressed and cleared appropriately to comply with Rule 606.