

Inspection Photos

Location Name: MorningStar Peterson 32-6 #14-4

Location ID: API 007-06242



Photo #1. Overview of the well location.

Inspection Photos

Location Name: MorningStar Peterson 32-6 #14-4

Location ID: API 007-06242



Photo #2. View of the #14-2 wellhead assembly.



Inspection Photos

Location Name: MorningStar Peterson 32-6 #14-4

Location ID: API 007-06242



Photo #3. View of weeds growing on tank containment berm.



Inspection Photos

Location Name: MorningStar Peterson 32-6 #14-4

Location ID: API 007-06242



Photo #4. View of raven nest on tank battery catwalk.

