

Inspection Photos

API: 099-06255

Operator: BERRY* WALTER V DBA BERRY ENERGY INC

Inspection Date: 7/11/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 099-06255 | Date: 7/11/2023

Inspection Photos



Photo 1. South side of the location facing northeast. This area does not have vegetation establishment which is approximately 100'x50'. This area likely has impacted soils from a possible spill.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06255 | Date: 7/11/2023

Inspection Photos



Photo 2. There is a pipe riser that remains at the north side of the location which has not been removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06255 | Date: 7/11/2023

Inspection Photos



Photo 3. Photo from previous inspection. Facing northwest approximately 1400 ft. northwest of the location. There are two pipe risers associated with the well site that have not been removed. All equipment/risers must be removed. Lat/Long:37.78859,-102.44911.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06255 | Date: 7/11/2023