

Inspection Photos

API: 099-06354

Operator: BERRY* WALTER V DBA BERRY ENERGY INC

Inspection Date: 7/11/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 099-06354 | Date: 7/11/2023

Inspection Photos



Photo 1. Drone aerial photo facing northeast toward the abandoned well location. The pits were have not been backfilled and reclaimed



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06354 | Date: 7/11/2023

Inspection Photos



Photo 2. Drone aerial photo facing southeast toward the abandoned well location. The pits were have not been backfilled and reclaimed



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06354 | Date: 7/11/2023

Inspection Photos



Photo 3. Facing west at the pit that was never backfilled and reclaimed. Berms around the pit are bare vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06354 | Date: 7/11/2023

Inspection Photos



Photo 4. Facing northwest toward a different pit. There is degraded plastic pit liner that remains in this pit.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06354 | Date: 7/11/2023

Inspection Photos



Photo 5. The degraded plastic pit liner remains in the pit.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06354 | Date: 7/11/2023

Inspection Photos



Photo 6. There are piles of soil material that remains from pit excavation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06354 | Date: 7/11/2023