

Inspection Photos

API: 099-06063

Operator: RENEGADE OIL & GAS COMPANY LLC

Inspection Date: 7/11/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 099-06063 | Date: 7/11/2023

Inspection Photos



Photo 1. Facing southeast toward the wellsite and tank battery.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06063 | Date: 7/11/2023

Inspection Photos



Photo 2. Sign is posted at the tank battery.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06063 | Date: 7/11/2023

Inspection Photos



Photo 3. There is oil stained soils at the tank pipe outlet. There is a plastic oil container that needs to be removed and disposed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06063 | Date: 7/11/2023

Inspection Photos



Photo 4. There is oil stained soil at the tank that needs to be cleaned up. It appears to have leaked out from the tank but no leak was observed at time of inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06063 | Date: 7/11/2023

Inspection Photos



Photo 5. There is oil staining that overtopped the open top tank. There is oil inside the tank and the tank is mislabeled as produced water.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06063 | Date: 7/11/2023

Inspection Photos



Photo 6. The netting on the open top tank is insufficient to prevent wildlife entry. There are openings at red arrow and oil level is over the netting.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06063 | Date: 7/11/2023

Inspection Photos



Photo 6. Facing toward the pumpjack.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06063 | Date: 7/11/2023