

Inspection Photos

API: 099-06045

Operator: RENEGADE OIL & GAS COMPANY LLC

Inspection Date: 7/11/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 099-06045 | Date: 7/11/2023

Inspection Photos



Photo 1. Facing southeast toward the wellsite. The fence at the tank battery is in disrepair shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06045 | Date: 7/11/2023

Inspection Photos



Photo 2. Facing east toward the separator shed. The fence at the shed is in disrepair and the shed wall is laying on the ground.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06045 | Date: 7/11/2023

Inspection Photos



Photo 3. Northeast corner of the location facing southwest. The location is fenced on three sides which is preventing the location to be reduced in size.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06045 | Date: 7/11/2023

Inspection Photos



Photo 4. Facing southwest at the location. There is an unused tank that needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06045 | Date: 7/11/2023

Inspection Photos



Photo 5. There is unused drilling rod that needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06045 | Date: 7/11/2023

Inspection Photos



Photo 6. Facing northeast standing at south side of the location. Unused areas of the location need to be reclaimed back to cropland.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06045 | Date: 7/11/2023

Inspection Photos



Photo 4. Aerial view of the location shows unused areas of the location below and to the right of red line could be put back into cropland.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06045 | Date: 7/11/2023