

Photo Log

S. Croix Operating, Inc. – #81490

Revenant #1 05-121-10111

May 1, 2023

Pre-Drill Migratory Bird Survey

Photo at location entrance – Cropland – Fallow Stubble, no evidence of migratory Bird nesting



Photo facing West – Representative of entire location conditions, Fallow Stubble, no evidence of migratory Bird nesting



Photo facing East – Fallow Stubble, no evidence of migratory Bird nesting



Photo facing NE – Fallow Stubble, no evidence of migratory Bird nesting



Photo Facing NW Fallow Stubble, no evidence of migratory Bird nesting



Photo Facing N – Fallow Stubble, no evidence of migratory Bird nesting



Photo at well stake – Fallow Stubble, no evidence of migratory Bird nesting

