

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403462613

Date Received:

07/12/2023

Spill report taken by:

Anderson, Laurel

Spill/Release Point ID:

477562

**SPILL/RELEASE REPORT (SUPPLEMENTAL)**

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 912.b. for reporting requirements of spills or releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas. Submit a Site Investigation and Remediation Workplan (Form 27) if Rule 913.c. applies.

**OPERATOR INFORMATION**

Name of Operator: PROVIDENCE OPERATING LLC DBA POCO OPERATING	Operator No: 10694	<b>Phone Numbers</b>
Address: 16400 DALLAS PARKWAY SUITE 400		Phone: (720) 256-8774
City: DALLAS State: TX Zip: 75428		Mobile: (720) 256-8774
Contact Person: Meghan Grimes		Email: mgrimes@providence-energy.com

Transfer of Operatorship: Pursuant to Rule 912.f, this Supplemental Form 19 is being submitted to designate the Buying Operator as the responsible Operator for this Spill and Release.

**INITIAL SPILL/RELEASE REPORT**

Initial Spill/Release Report Doc# 403451865

Initial Report Date: 07/02/2023 Date of Discovery: 07/01/2023 Spill Type: Recent Spill

**Spill/Release Point Location:**

QTRQTR NENW SEC 22 TWP 1N RNG 65W MERIDIAN 6

Latitude: 40.043933 Longitude: -104.651578

Municipality (if within municipal boundaries): County: WELD

Enter Lat./long measurement of the actual Spill/Release Point. Lat./Long. Data shall meet standards of Rule 216.

**Reference Location:**

Facility Type: TANK BATTERY  Facility/Location ID No 441625

Spill/Release Point Name:  Well API No. (Only if the reference facility is well) 05- -

No Existing Facility or Location ID No.

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0 Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0 Estimated Produced Water Spill Volume(bbl): >=5 and <100

Estimated Other E&P Waste Spill Volume(bbl): 0 Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: Approximately 20Bbbls of rain water and clean produced water

Has the subject Spill/Release been controlled at the time of reporting? Yes

**Land Use:**

Current Land Use: NON-CROP LAND Other(Specify):

Weather Condition: 65\* passing clouds

Surface Owner: FEE Other(Specify): Lawrence and Roberta Long

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

A pin hole leak was discovered on the water tank access door. All produced water stayed within containment. Total volume of water removed was approximately 20Bbls however this included some rain water from ongoing weather events. Water was sent to oil tanks until the hole can be repaired. Repairs occurring today (7/2/2023).

**List of Agencies and Other Parties Notified Pursuant to Rule 912.b.(7)-(11):**

**OTHER NOTIFICATIONS**

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
7/2/2023	Surface Owner	Lawrence Long	303-549-7161	left voicemail
7/2/2023	Weld County OEM		-	online spill report form filed
7/2/2023	Weld County Oil and Gas	Jason Maxey	970-400-3580	emailed oged@weldgov.com - no response at time of report

**REPORT CRITERIA**

**Rule 912.b.(1) Report to the Director (select all criteria that apply):**

No Rule 912.b.(1).A: A Spill or Release of any size that impacts or threatens to impact any Waters of the State, Public Water System, residence or occupied structure, livestock, wildlife, or publicly-maintained road.

Waters of the State: \_\_\_\_\_ Public Water System: \_\_\_\_\_  
Residence or Occupied Structure: \_\_\_\_\_ Livestock: \_\_\_\_\_  
Wildlife: \_\_\_\_\_ Publicly-Maintained Road: \_\_\_\_\_

No Rule 912.b.(1).B: A Spill or Release in which 1 barrel or more of E&P Waste or produced fluids is spilled or released outside of berms or other secondary containment.

Yes Rule 912.b.(1).C: A Spill or Release of 5 barrels or more of E&P Waste or produced Fluids regardless of whether the Spill or Release is completely contained within berms or other secondary containment.

No Rule 912.b.(1).D: Within 6 hours of discovery, a Grade 1 Gas Leak. For a Grade 1 Gas Leak from a Flowline, the Operator also must submit the Form 19 – Initial, document number on a Form 44, Flowline Report, for the Grade 1 Gas Leak

Enter the approximate time of discovery \_\_\_\_\_ (HH:MM)  
Enter the Document Number of the Grade 1 Gas Leak Report, Form 44 \_\_\_\_\_  
Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? \_\_\_\_\_  
Enter the Document Number of the Initial Accident Report, Form 22 \_\_\_\_\_  
Was there damage during excavation? \_\_\_\_\_  
Was CO 811 notified prior to excavation? \_\_\_\_\_

No Rule 912.b.(1).E: The discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards.

Estimated Volume of Impacted Solids (cu. yd.): \_\_\_\_\_

No Rule 912.b.(1).F: The discovery of impacted Waters of the State, including Groundwater. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards. The presence of free product or hydrocarbon sheen on Groundwater or surface water is reportable. The presence of contaminated soil in contact with Groundwater or surface water is reportable. Check all that apply:

- The presence of free product or hydrocarbon sheen Surface Water
- The presence of free product or hydrocarbon sheen on Groundwater
- The presence of contaminated soil in contact with Groundwater
- The presence of contaminated soil in contact with Surface water

No	Rule 912.b.(1).G: A suspected or actual Spill or Release of any volume where the volume cannot be immediately determined, including a spill or release of any volume that daylights from the subsurface.
No	Rule 912.b.(1).H: Spill or Release resulting in vaporized hydrocarbon mists that leave the Oil and Gas Location or Off-Location Flowline right of way from an Oil and Gas Location and impacts or threatens to impact off-location property.  <input type="checkbox"/> Areas offsite of Oil & Gas Location <input type="checkbox"/> Off-Location Flowline right of way
No	Rule 912.b.(1).I: A Release of natural gas that results in an accumulation of soil gas or gas seeps.
No	Rule 912.b.(1).J: A Release that results in natural gas in Groundwater.

### SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: <u>07/12/2023</u>		
<b>FLUIDS</b>	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	<u>0</u>	<u>0</u>	<input type="checkbox"/>
CONDENSATE	<u>0</u>	<u>0</u>	<input type="checkbox"/>
PRODUCED WATER	<u>20</u>	<u>20</u>	<input type="checkbox"/>
DRILLING FLUID	<u>0</u>	<u>0</u>	<input type="checkbox"/>
FLOW BACK FLUID	<u>0</u>	<u>0</u>	<input type="checkbox"/>
OTHER E&P WASTE	<u>0</u>	<u>0</u>	<input type="checkbox"/>
specify: _____			
Was spill/release completely contained within berms or secondary containment? <u>YES</u> Was an Emergency Pit constructed? <u>NO</u>			
<i>Secondary containment, including walls &amp; floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.</i>			
<b>A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit</b>			
Impacted Media (Check all that apply) <input type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature			
Surface Area Impacted: Length of Impact (feet): _____		Width of Impact (feet): _____	
Depth of Impact (feet BGS): _____		Depth of Impact (inches BGS): _____	
How was extent determined?			
All produced water was within containment. No extent to be determined outside of containment.			
Soil/Geology Description:			
No soil was impacted.			
Depth to Groundwater (feet BGS) <u>20</u>		Number Water Wells within 1/2 mile radius: <u>5</u>	
If less than 1 mile, distance in feet to nearest		Water Well <u>1200</u> None <input type="checkbox"/>	Surface Water <u>100</u> None <input type="checkbox"/>
		Wetlands _____ None <input checked="" type="checkbox"/>	Springs _____ None <input checked="" type="checkbox"/>
		Livestock _____ None <input checked="" type="checkbox"/>	Occupied Building <u>1065</u> None <input type="checkbox"/>
Additional Spill Details Not Provided Above:			
Water well used for static water level permit #245545.			

### CORRECTIVE ACTIONS

#1 Supplemental Report Date: 07/12/2023

Root Cause of Spill/Release Equipment Failure

Other (specify)

Type of Equipment at Point of Spill/Release: Other

If "Other" selected above, specify or describe here:

Water Tank

Describe Incident & Root Cause (include specific equipment and point of failure)

Pin hole leak in water tank discovered and has been repaired.

Describe measures taken to prevent the problem(s) from reoccurring:

Equipment has been repaired and regular observation of equipment will continue to proactively identify potential failures on an ongoing basis. No soil was excavated however produced water was hydrovac'd out and disposed of. See attached manifest.

Volume of Soil Excavated (cubic yards): 0

Disposition of Excavated Soil (attach documentation) [X] Offsite Disposal [ ] Onsite Treatment [ ] Other (specify)

Volume of Impacted Ground Water Removed (bbls): 0

Volume of Impacted Surface Water Removed (bbls): 0

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

- Basis for Closure: [ ] Corrective Actions Completed (documentation attached, check all that apply) [ ] Horizontal and Vertical extents of impacts have been delineated. [ ] Documentation of compliance with Table 915-1 is attached. [ ] All E&P Waste has been properly treated or disposed. [ ] Work proceeding under an approved Form 27 (Rule 912.c). Form 27 Remediation Project No: [ ] SUSPECTED Spill/Release did not occur or was below Rule 912.a.(5) reporting thresholds.

OPERATOR COMMENTS:

Per COA an aerial map is attached. Per COA coordinates have been updated to reflect the location of the spill. Per COA we have confirmed that no impacts were discovered outside of containment. COA regarding details of secondary containment are still being addressed - per photo attached the tank is within secondary containment. Due to recent acquisition of this location I am still working to find details on materials used for building and lining of the containment.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Meghan Grimes Print Name: Meghan Grimes Title: Sr. Manager ESG Date: 07/12/2023 Email: mgrimes@providence-energy.com

**COA Type****Description**

0 COA	

**Attachment List****Att Doc Num****Name**

403462625	AERIAL IMAGE
403462626	DISPOSAL MANIFEST
403462632	PHOTO DOCUMENTATION

Total Attach: 3 Files

**General Comments****User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)