

## Inspection Photos

Operator: CAERUS PICEANCE LLC – 10456


Location Name: PICEANCE CREEK UNIT #T21X-7G

Location ID: 316247 API #: 05-103-10100

Inspection Date: 7/11/2023 Inspection Doc#: 693806325



Injection wellhead during MIT



Form 21 field copy

