



WELL SITE INSPECTION FORM

99999999

WELL NAME Kemery J-9  
OPERATOR Amax Petro  
LOCATION SWSE 20-7N-53W  
FIELD Atwood

API NUMBER 05 - 075 - 5294  
PERMIT NUMBER \_\_\_\_\_  
COUNTY Logan  
INSPECTOR SP

AL/PA/DA INSPECTION RESULTS:

PASS(Y) ☒ FAIL(N) \_\_\_\_\_ DATE 8/23/88

WELL STATUS:

FN \_\_\_\_\_ FD \_\_\_\_\_ WO \_\_\_\_\_

=====

DATE OF INSPECTION BEFORE/DURING DRILLING \_\_\_\_\_

CASING SIZE \_\_\_\_\_ DEPTH SET \_\_\_\_\_ CMT VOL \_\_\_\_\_ WOC \_\_\_\_\_  
CONSISTENT WITH APD CASING PROGRAM? \_\_\_\_\_ RETURNS \_\_\_\_\_  
RIG \_\_\_\_\_ BOP'S \_\_\_\_\_ CONTACT \_\_\_\_\_

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION \_\_\_\_\_

PIPE SET? \_\_\_\_\_ COMPLETION RIG/ACTIVITY \_\_\_\_\_  
DRILLING PITS: CLOSED \_\_\_\_\_ OPEN \_\_\_\_\_ WELLHEAD SYSTEM INSTALLED \_\_\_\_\_  
TANK ID: YES \_\_\_\_\_ NO \_\_\_\_\_ NA \_\_\_\_\_ WELL SIGN: YES \_\_\_\_\_ NO \_\_\_\_\_  
SKIM PIT: \_\_\_\_\_ gal TANKS: ( ) \_\_\_\_\_ bbls  
EQUIPMENT \_\_\_\_\_  
BRADENHEAD PRESSURE \_\_\_\_\_ FLUID: NO \_\_\_\_\_ YES \_\_\_\_\_ TYPE \_\_\_\_\_  
METER RUN: YES \_\_\_\_\_ NO \_\_\_\_\_ WELL STATUS: PR \_\_\_\_\_ TA \_\_\_\_\_ SI \_\_\_\_\_ WELL CAT 3- \_\_\_\_\_

AL/PA/DA INSPECTION

DATE PLUGGED: \_\_\_\_\_ DATE PERMIT EXPIRED: \_\_\_\_\_  
HOLE PLUGGED: YES ☒ NO \_\_\_\_\_ PITS BACKFILLED: YES ☒ NO \_\_\_\_\_  
MATERIAL BURIED: YES ☒ NO \_\_\_\_\_ NA \_\_\_\_\_ SITE CLEAN: YES \_\_\_\_\_ NO ☒  
BOND RELEASE OK: YES ☒ NO \_\_\_\_\_ FED \_\_\_\_\_ HOLE MARKER: YES \_\_\_\_\_ NO \_\_\_\_\_

DATE OF SAFETY/STATUS INSPECTION \_\_\_\_\_

COMMENTS \* old pipe/fence at old bath site  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



00202894