

Inspection Photos
Location Name: Wildhorse 02-0214 PAD
Location ID: 428750



Photo 1 – Signs at Entrance



Photo 2 – Pumping Units

Inspection Photos
Location Name: Wildhorse 02-0214 PAD
Location ID: 428750




Photo 3 – 02-0214H Wellhead




Photo 4 – 02-0214AH Wellhead

Inspection Photos
Location Name: Wildhorse 02-0214 PAD
Location ID: 428750



Photo 5 – 02-0214H Exhaust – Stained Soil



Photo 6 – 02-0214H Gas Engine House

Inspection Photos
Location Name: Wildhorse 02-0214 PAD
Location ID: 428750



Photo 7 – 02-0214AH Stained Soil at Gas Engine



Photo 8 – Flares and ECD

Inspection Photos
Location Name: Castor 7-59-12 PAD
Location ID: 465272



Photo 9 – Heater Treaters



Photo 10 – Tank Battery

Inspection Photos
Location Name: Wildhorse 02-0214 PAD
Location ID: 428750



Photo 11 – Tank Battery Sign



Photo 12 – Tank Battery Sign

