

Inspection Photos
Location Name: Behring #1
Location ID: 317496



Photo 1 – Wellhead



Photo 2 – Pumping Unit



Inspection Photos
Location Name: Behring #1
Location ID: 317496



Photo 3 – Tank Battery - NFPA Label



Photo 4 – Tank Battery Sign

Inspection Photos
Location Name: Behring #1
Location ID: 317496



Photo 5 – Heater Treater



Photo 4 – Produced Water Tank

Inspection Photos
Location Name: Behring #1
Location ID: 317496



Photo 7 – Pit Area



Photo 8 – Tank Catwalk and Stairs and Gas Meter House

Inspection Photos
Location Name: Behring #1
Location ID: 317496



Photo 9 – Pumping Unit



Photo 10 – Pumping Unit