

Inspection Photos
Location Name: State Antelope 41-3HZ
Location ID: 422884



Photo 1 – Pumping Unit



Photo 2 – Pumping Unit



Inspection Photos
Location Name: State Antelope 41-3HZ
Location ID: 422884




Photo 3 – Stained Soil, Unmarked Riser and Unused Master Valves



Photo 4 – Wellhead Sign

