

Inspection Photos
Location Name: Antelope P-17 PAD
Location ID: 428964



Photo 1 – Tank Battery Signs



Photo 2 – Sign at Entrance

Inspection Photos
Location Name: Antelope P-17 PAD
Location ID: 428964



Photo 3 – Tank Battery



Photo 4 – Pumping Unit

Inspection Photos
Location Name: Antelope P-17 PAD
Location ID: 428964



Photo 5 – Wellheads



Photo 6 – Unused Equipment

Inspection Photos
Location Name: Antelope P-17 PAD
Location ID: 428964



Photo 7 – Compressor and Gas Lift Injection Meters



Photo 8 – Stained Soil at Compressor and Locate Flags

Inspection Photos
Location Name: Antelope P-17 PAD
Location ID: 428964



Photo 9 – Stained Soil Compressor and Locate Flags



Photo 10 – Compressor Day Tank Wildlife Netting and Debris

Inspection Photos
Location Name: Antelope P-17 PAD
Location ID: 428964



Photo 11 – Compressor Day Tank Wildlife Netting and Debris



Photo 12 – ECDs and Separators

Inspection Photos
Location Name: Antelope P-17 PAD
Location ID: 428964



Photo 13 – Pig Stations



Photo 14 – Located Flags

Inspection Photos
Location Name: Antelope P-17 PAD
Location ID: 428964



Photo 15 – Produced Water Vaults



Photo 16 – Content and Capacity Labels