


## Inspection Photos

Location Name: Bledsoe SWD 1-18-3-43

Location ID:



1. Well sign with emergency contact number.



2. Insulated wellhead building.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Inspection Photos**  
**Location Name: Bledsoe SWD 1-18-3-43**  
**Location ID:**



**3. View of well inside building.**



**4. View of Braden Head gauge.**



**Inspection Photos**  
**Location Name: Bledsoe SWD 1-18-3-43**  
**Location ID:**



**5. View of casing gauge.**



**6. View of valve installed in tubing missing gauge.**

**Inspection Photos**  
**Location Name: Bledsoe SWD 1-18-3-43**  
**Location ID:**



**7. View of one of four located and marked deadmen.**



**8. Metal building containing injection equipment.**



**Inspection Photos**  
**Location Name: Bledsoe SWD 1-18-3-43**  
**Location ID:**



**9. Produced water filter.**



**10. Injection pump.**

**Inspection Photos**  
**Location Name: Bledsoe SWD 1-18-3-43**  
**Location ID:**



**11. Tank located outside injection building with no signage. Note the lighter color at the crown of the tank. It is full.**



**12. 400 BBL produced water storage tanks. One steel and one fiberglass. Note vegetation inside and on berms.**



**Inspection Photos**  
**Location Name: Bledsoe SWD 1-18-3-43**  
**Location ID:**



**13. 210 BBL fiberglass storage tank.**



**14. View of the backside of tank battery. Note vegetation.**

**Inspection Photos**  
**Location Name: Bledsoe SWD 1-18-3-43**  
**Location ID:**



**15. Tipped over trash can releasing trash and debris onto location.**



**16. Intense storms in the area may have blown these over. Location needs to be monitored and checked after these weather events to ensure integrity of equipment, buildings, and resources.**