

# Final Reclamation and Stormwater Inspection

Date: 07/11/2023

Operator: MARKUS PRODUCTION, INC - 53790

Location ID: 327473

Inspection Document #: 708200377

Weld County, CO

SWNE Section 7 T7N R59W

Dylan Edwardson  
Reclamation Specialist, ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Livengood 7-7  
Location ID: 327473



**Photo 1.** The former well location does not appear to have been reclaimed with the presence of gravel, undesirable vegetation (russian thistle and kochia), and the location does not appear to have been contoured or graded to reflect adjacent areas.

Inspection Photos  
Location Name: Livengood 7-7  
Location ID: 327473



**Photo 2.** See comments in Photo 2.

Inspection Photos  
Location Name: Livengood 7-7  
Location ID: 327473



**Photo 3.** See comments in Photo 2.

Inspection Photos  
Location Name: Livengood 7-7  
Location ID: 327473



**Photo 4.** See comments in Photo 1; red line indicates areas needing additional contouring/grading work.

Inspection Photos  
Location Name: Livengood 7-7  
Location ID: 327473



**Photo 5.** Access road leading south of location. This access road will need to be reclaimed. See FIR Doc #708200376 for additional information.

Inspection Photos  
Location Name: Livengood 7-7  
Location ID: 327473



**Photo 6.** Access road leading north of location; see comments in Photo 5.