

Inspection Photos
Location Name: TREBOR B/11-22
Location ID: 414327



Photo #1

Trebor B 11-22 (123-30733) Wellsite

Temporarily Abandoned | TA

CA: Weeds need mitigated



Photo #2

Trebor B 11-22 Battery site

Inactive | Shut-down

Inspection Photos
Location Name: TREBOR B/11-22
Location ID: 414327



Photo #3
Trebor B 11-22 Battery site
Inactive | Shut-down
Tank(s): SE corner



Photo #4
Trebor B 11-22 Battery site
Inactive | Shut-down
Separator(s), ECD(s)

Inspection Photos
Location Name: TREBOR B/11-22
Location ID: 414327



Photo #5

Trebor B 11-22 Battery site

Inactive | Shut-down

Battery sign