



00382043

Phone 522-1410

Donnelly Casing Pulling Co.

P.O. Box 791
Sterling, Colorado 80751

RECEIVED

JAN 4 1977

Bob Donnelly

SOLD TO Mr. Art Guida
2050 Western Federal Bldg.
Denver, Colorado 80202

COLO. OIL & GAS CONS. COMM.
INVOICE DATE 12-31-76

WELL Van Gundy #5

INVOICE NO. 102

BEST IMAGE AVAILABLE

Pulled rods & tubing		\$ 550.00
3810' 4½" OD Casing @	35¢ per foot	1333.50
Cement, 30 sacks @	\$3.50 each + tax	108.15
Water Truck, 5 hours @	\$20.00 per hour	100.00
Day Work, 30 hours @	\$20.00 per hour	600.00
		<u>\$2691.65</u>

DATE	DAY WORK	REMARKS
12-16-76	2 hours	Moved rig on Van Gundy #5. Dug deadmen.
12-17-76	0 hours	Pulled rods and 120 joints tubing.
12-18-76	0 hours	Pulled 39 joints. Had trouble with the packer.
12-20-76	9 hours	Tore down power tongs. Dug cellar. Rigged up Worked pipe. Ran sand at 4800'. Set 5 sacks cement on top of sand. Water truck, 5 hours.
12-21-76	9 hours	Worked pipe to 35" tension. Ran shot to 4000'. Worked pipe.
12-22-76	6 hours	Worked pipe. Ran shot to 3900' and to 3800'. Worked pipe loose. Pulled 39 joints.
12-23-76	4 hours	Pulled 83 joints. Tore down, jacks and rig. Set 15 sacks cement in bottom of surface at 95'. Mudded to 28'. Set 10 sacks cement in top. Cut off pipe 4' below ground level. Welded on plate.

WELL COMPLETE

THANK YOU