

Inspection Photos
Location Name: Bledsoe 8-18-3-43
Location ID: 125-09172



1. Well sign.



2. View of wellhead. Casing valve closed.

Inspection Photos
Location Name: Bledsoe 8-18-3-43
Location ID: 125-09172



3. Pump Jack and Meter/Separator Shed.



4. Pump Jack Prime Mover Gas Motor.

Inspection Photos
Location Name: Bledsoe 8-18-3-43
Location ID: 125-09172




5. View of Vertical Separator.



6. View of Gas Meter Run.

Inspection Photos
Location Name: Bledsoe 8-18-3-43
Location ID: 125-09172



7. View of Chart Dated 12-2-22 in Meter Box.



8. One of the four Anchor Markers at anchor but broken over.