

Inspection Photos
Location Name: Bledsoe 16-18-3-43
Location ID: 125-09183



1. Well sign inside fencing.



2. View of Wellhead. Note vegetation inside fencing.

Inspection Photos
Location Name: Bledsoe 16-18-3-43
Location ID: 125-09183



3. View of Pump Jack with motor removed.



4. View of Gas Meter Run and Vertical Separator inside shed.

Inspection Photos
Location Name: Bledsoe 16-18-3-43
Location ID: 125-09183



5. Gas Chart that was in Meter Box at time of inspection.



6. Surface casing valve open to atmosphere.