

# Final Reclamation Inspection

July 13, 2023

Operator: Noble Energy # 100322

Location ID:457758

Inspection Document #:709400369

Weld, County

SWNE, Section 1, 2N65W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: Dechant State 15C-1HZ

Location ID: 457758



Photo 1. Photo taken of location sign.

Photo 2. Photo of tank battery..



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 709400369



Inspection Photos  
Location Name: Dechant State 15C-1HZ  
Location ID: 457758



**Photo 3. Photo taken of actively leaking crude oil tank, from hole in tank side wall.**



**Photo 4. Photo taken of unused equipment on site.**