

# Inspection Photos

API: 043-40025

Operator: JAVERNICK OIL

Inspection Date: 7/13/2023



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 043-40025 | Date: 7/13/2023

## Inspection Photos



**Photo 1.** Facing south at the abandoned wellsite. The site remain not reclaimed and there are undesirable weeds and bare soil in this area of the wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40025 | Date: 7/13/2023



## Inspection Photos



**Photo 2.** Facing southeast at the wellsite. There is bare soils and scattered debris remnants that remain.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40025 | Date: 7/13/2023



## Inspection Photos



**Photo 3.** View of ground cover shows metal cable, nails and debris that remains.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40025 | Date: 7/13/2023