

Inspection Photos

API# 043-06212

Operator: INCREMENTAL OIL & GAS
(FLORENCE) LLC

Inspection Date: 7/13/2023



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API# 043-06212 | Date: 7/13/2023

Inspection Photos



Photo 1. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API# 043-06212 | Date: 7/13/2023

Inspection Photos



Photo 2. There are undesirable weeds (Russian thistle) growing throughout the location and around the equipment that need to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API# 043-06212 | Date: 7/13/2023

Inspection Photos



Photo 3. There are undesirable weeds (Russian thistle) growing throughout the location and around the equipment that need to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API# 043-06212 | Date: 7/13/2023