

Inspection Photos

API: 043-06207

Operator: JAVERNICK OIL

Inspection Date: 7/13/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 043-06207 | Date: 7/13/2023

Inspection Photos



Inspection Photos



Photo 2. East side of the location facing south. Gravel remains at the location and there are undesirable weeds growing in the gravel area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06207 | Date: 7/13/2023

Inspection Photos



Photo 3. Southeast corner of the location facing north along the fill slope. There are undesirable growing along the fill slope that need to be controlled. The location has not been recontoured.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06207 | Date: 7/13/2023

Inspection Photos



Photo 4. Facing northwest at the location. This is the area of the former pit which was backfilled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06207 | Date: 7/13/2023

Inspection Photos



Photo 5. There are two gravel pile at the remain at the northwest corner of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06207 | Date: 7/13/2023

Inspection Photos



Photo 6. West side of the location facing southeast.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06207 | Date: 7/13/2023

Inspection Photos



Photo 7. Facing northeast toward the beginning of the access road. Gravel remains along the road and there are undesirable weeds.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06207 | Date: 7/13/2023