

Inspection Photos
Location Name: Lind 26-D Pad
Location ID: 458152



Lease road entrance sign



Colorado Oil & Gas Conservation Commission
40.55181, -104.85277, 1483.5m, 199°
07/17/2023 11:26:57

Inspection Photos
Location Name: Lind 26-D Pad
Location ID: 458152



Bulk lube oil tank wildlife protection



Unused equipment

Inspection Photos
Location Name: Lind 26-D Pad
Location ID: 458152



Unused equipment



Unused equipment