

**Inspection Photos**  
**Location Name: Antelope J-19 PAD**  
**Location ID: 430139**



**Photo 1 – Tank Battery Signs at Entrance**



**Photo 2 – Wellheads**

**Inspection Photos**  
**Location Name: Antelope J-19 PAD**  
**Location ID: 430139**



**Photo 3 – J-F-19HZ Well Sign**



**Photo 4 – O-K-19HZ Well Sign**



**Inspection Photos**  
**Location Name: Antelope J-19 PAD**  
**Location ID: 430139**



**Photo 5 – Line Heater – Missing Bird Protector**



**Photo 6 – Pig Station – Locate Flags**

**Inspection Photos**  
**Location Name: Antelope J-19 PAD**  
**Location ID: 430139**



**Photo 7 – Gas Lift Injection Meter House**



**Photo 8 – Separators**





**Inspection Photos**  
**Location Name: Antelope J-19 PAD**  
**Location ID: 430139**



**Photo 9 – Tumbleweeds Debris**



**Photo 10 – Tumbleweeds Debris**

**Inspection Photos**  
**Location Name: Antelope J-19 PAD**  
**Location ID: 430139**



**Photo 11 – Separators**



**Photo 12 – Locate Flags**



Inspection Photos  
Location Name: Antelope J-19 PAD  
Location ID: 430139



Photo 13 – Tank Battery Signs

Photo 14 – Tank Battery Signs

**Inspection Photos**  
**Location Name: Antelope J-19 PAD**  
**Location ID: 430139**



**Photo 15 – Tank Battery**




**Photo 16 – Tank Battery**



**Inspection Photos**  
**Location Name: Antelope P-17 PAD**  
**Location ID: 428964**



**Photo 17 – Tank Battery Sign**



**Photo 18 – NFPA Labels on Tanks 220508 & 220509**

**Inspection Photos**  
**Location Name: Antelope P-17 PAD**  
**Location ID: 428964**



**Photo 19 – ECDs**