

Inspection Photos
Location Name: State Antelope 14-19 PAD
Location ID: 413458



Photo 1 – Tank Battery Signs at Entrance



Photo 2 – Wellhead – Tumbleweed Debris

Inspection Photos
Location Name: State Antelope 14-19 PAD
Location ID: 413458




Photo 3 – Wellheads – Tumbleweed Debris



Photo 4 – Unmarked Risers

Inspection Photos
Location Name: State Antelope 14-19 PAD
Location ID: 413458



Photo 5 – Gas Lift Injection Meter House