

**Inspection Photos**  
**Location Name: Antelope T-19 PAD**  
**Location ID: 458201**



**Photo 1 – Unused Wood Crate**



**Photo 2 – Wellheads**

Inspection Photos  
Location Name: Antelope T-19 PAD  
Location ID: 458201



Photo 3 – Wellheads



Photo 4 – Maintenance Tank

**Inspection Photos**  
**Location Name: State Antelope 14-19 PAD**  
**Location ID: 413458**



**Photo 5 – Separators**



**Photo 6 – Gas Lift Injection Meter House**

Inspection Photos  
Location Name: State Antelope 14-19 PAD  
Location ID: 413458



Photo 7 – Pig Stations

Photo 8 – Signs at Entrance