

**Inspection Photos**  
**Location Name: Antelope O-20 PAD**  
**Location ID: 459884**



**Photo 1 – Separators**



**Photo 2 – Instrumental Air Unit and Gas Lift Injection Meter House**

**Inspection Photos**  
**Location Name: Antelope O-20 PAD**  
**Location ID: 459884**



**Photo 3 – Maintenance Tank**



**Photo 4 – Wellheads**



**Inspection Photos**  
**Location Name: Antelope O-20 PAD**  
**Location ID: 459884**



**Photo 5 – Tumbleweed Debris**



**Photo 6 – Tumbleweed Debris**

**Inspection Photos**  
**Location Name: Antelope O-20 PAD**  
**Location ID: 459884**



**Photo 7 – Trash**