



WELL SITE INSPECTION FORM

Well Name Rogers 1 API Number 05-017-7417
Operator Mull Permit # _____
Location SWNE 8-165-50W County Cheyenne
Field _____ Inspector EBB

AL/PA/DA Inspection Results:

Pass(Y) _____ Fail(N) _____ Date _____ ND _____ DG ☒ WO _____ PR _____ SI _____ TA _____

Well Status:

Date of Inspection Before/During Drilling 4-8-94 5 20 pm

Surf. Csg. Size _____ Setting Depth _____ Cmt. Vol. _____ WOC time _____
Consistent with APD casing Program? YES _____ NO _____ Returns _____
Rig Kudu BOP'S _____ Stage Tool Depth _____ Cmt. Vol. _____

Date of Inspection Before/During/After Completion _____

Prod. Csg. Set? _____ Completion Rig/Activity _____
Drilling Pits: Closed _____ Open _____ Wellhead Installed: _____ Sign: Yes _____ No _____
Tank ID: Yes _____ No _____ N/A _____ Skim Tank/Pit: _____ Prod. Tanks: () _____ BBLs
Equipment _____ Meter Run: Yes _____ No _____
Bradenhead Press: _____ Fluid: No _____ Yes _____ Type _____ Well Cat. _____

AL/PA/DA Inspection

Date Plugged: _____	Date Permit Expired: _____
Hole Plugged: Yes _____ No _____	Pits Backfilled: Yes _____ No _____
Material Buried: Yes _____ No _____ N/A _____	Site Clean: Yes _____ No _____
Bond Release OK: Yes _____ No _____ Fed _____	Hole Marker: Yes _____ No _____

Date of Safety/Status Inspection _____

Comments: Kudu MURRT Sandy location. 2 mile new road.

Violations: Yes _____ No _____ Notice Sent: Yes _____ No _____ Date Sent: _____