

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 206-20 Pad

Location ID: 335217



Photo # 3115 From entrance to location



Photo # 3116 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 206-20 Pad

Location ID: 335217



Photo # 3119 Location



Photo # 3120 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 206-20 Pad

Location ID: 335217



Photo # 3129 Location



Photo # 3130 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 206-20 Pad

Location ID: 335217




Photo # 3121 Debris



Photo # 3127 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 206-20 Pad

Location ID: 335217



Photo # 3123 Stained soils & gravel



Photo # 3124 Stained soils & gravel

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 206-20 Pad

Location ID: 335217



Photo # 3126 Stained soils & gravel