

Inspection Photos

7/10/2023

Operator: LARAMIE ENERGY LLC #10433

Location Number: 452807

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location Number: 452807



Photo 1: Example of tanks on Location either missing required labeling, or labels lack required information per Rule 605.h.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location Number: 452807



Photo 2: Trash/debris stored next to wells.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location Number: 452807



Photo 3: Stained soils at wells.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location Number: 452807



Photo 4: Uncapped/exposed line observed at separator equipment.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location Number: 452807



Photo 5: Porta-johns stored at the Location entrance lack required spill prevention/containment BMPs.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location Number: 452807



Photo 6: Spill observed at frac lines south of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location Number: 452807



Photo 7: Spill observed at frac lines south of the Location. Fluids observed leaking into the blue bucket containing dark fluids.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources