

Inspection Photos
Location Name: Antelope 11-20 PAD
Location ID: 424418



Photo 1 – Wellheads – Tumbleweed Debris



Photo 2 – Wellheads

Inspection Photos
Location Name: Antelope 11-20 PAD
Location ID: 424418



Photo 3 – Unmarked Risers at Wellheads



Photo 4 – Separators and ECD

Inspection Photos
Location Name: Antelope 11-20 PAD
Location ID: 424418



Photo 5 – Tank Battery



Photo 6 – Tank Battery Signs



Inspection Photos
Location Name: Antelope 11-20 PAD
Location ID: 424418



Photo 7 – Tank Battery Signs

