

Inspection Photos  
Location Name: Antelope I-17 PAD  
Location ID: 420880



Photo 1 – Signs at Entrance




Photo 2 – Wellhead

**Inspection Photos**  
**Location Name: Antelope I-17 PAD**  
**Location ID: 420880**



**Photo 3 – Wellheads**




**Photo 4 – Wellheads**

**Inspection Photos**  
**Location Name: Antelope I-17 PAD**  
**Location ID: 420880**



**Photo 5 – Tank Battery**



**Photo 6 – Tank Battery Signs**



**Inspection Photos**  
**Location Name: Antelope 11-20 PAD**  
**Location ID: 424418**



**Photo 7 – Tank Battery Signs**



**Photo 8 – Separator – Tumbleweed Debris**

**Inspection Photos**  
**Location Name: Antelope 11-20 PAD**  
**Location ID: 424418**



**Photo 9 – ECD**



**Photo 10 – Separator – Tumbleweed Debris**