

Inspection Photos
Location Name: Middlepark 18-5-4L
Location ID: 442024



Photo 1 – Wellhead



Photo 2 – Stained Soil – Backpressure and Needle Valves appear to be leaking onto ground

Inspection Photos
Location Name: Middlepark 18-5-4L
Location ID: 442024



Photo 3 – Wellhead Sign



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources